



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Kathleen Clarke
Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

October 11, 2000

TO: Minerals File

FROM: Doug Jensen, Senior Reclamation Specialist *D. Jensen*

RE: Site Inspection, North Lily Mining Company, Tintic Project, M/023/007, Juab County, Utah

Date of Inspection: October 5, 2000
Time of Inspection: 9:45 a.m.
Conditions: Warm and Breezy
Participants: Doug Jensen, DOGM

Purpose of Inspection: Assess site conditions prior to bi-monthly telephone conference

Arrived at the site to check any changes that had taken place since my last visit. Elwin's vehicle was at the gate when I arrived but I never encountered him during my visit.

The conditions at the site were basically unchanged. The mister sprays in the preg and overflow pond were both running. The repaired rips in the overflow pond had been draped with pieces of PVC liner. This had been done to protect the areas that had previously been damaged by the wind. The drapes will help to protect the torn areas from potential wind lift and also from the overspray of the misters. Because the torn areas are draped, any moisture that falls on the damaged areas will shed and not run under the pond liner. Additional sandbags had been added to the drapes which will help hold the draping material and the torn liners down when the wind blows.

While at the site, I walked over the site of the proposed infiltration area. One major problem that is immediately apparent is that the power line, supplying power to the site, runs through this area. This fact should be noted because of the concentration of the leach lines proposed in this area, providing that this area is chosen for the site of the infiltration gallery. Also, the proximity to the highway may also become a problem if the gallery requires 12,800 feet of leach lines, as indicated in the preliminary design.

No other obvious changes were noted during the visit.

jb
cc: Steve Fletcher, North Lily Mining
Walt Shubert, North Lily Mining
Bob Bayer, JBR
Beth Wondimu, DWQ
Pam Grubaugh-Littig, DOGM
Wayne Hedberg, DOGM

North Lily\oct5.ins

0026